



Product is neat, tidy and effective.
Note that vertical alignment is achieved by correct use of stabilising wedges inside the stanchion holes.



Product is distracting and poorly presented.
Shade cloth solutions rarely result in an
effective screen.



Timber panels need to be maintained, especially when installed for longer periods.



Temporary fence panels mounted on a steel barrier system. It is unlikely that the method of mounting is approved by the barrier manufacturer and could compromise the barrier performance. Horizontal rails constitute a potential spearing hazard and are not permitted.



Temporary fence panels mounted on PCBs.
Horizontal rails constitute a potential spearing
hazard and are not permitted.



**Road Safety
Audit Specialists**

- > Over 2,000 Road Safety Audits completed
- > 15 Senior Road Safety Auditors with specific expertise
- > Thematic audit experts – motorcycle, bicycle, walking, accessibility
- > Road Safety Audits based on the Safe System approach

Get in contact [SafeSystemSolutions.com.au](https://www.SafeSystemSolutions.com.au)
VIC | QLD | NSW | TAS | NT | SA | NZ (Safe System Audits)